

General Environmental Incident Summary

Incident: 3480 **Date/Time Notice:** 9/30/2014 **DEM Incident No:**
Responsible Party: Pinkys Aggregate
Date Incident: 9/30/2014 **Time Incident:** 1:00 pm **Duration:** 1 hours
County: Rolette **Twp:** 164 **Rng:** 69 **Sec:** 27 **Qtr:**
Lat: 48.99702 **Long:** -99.57442 **Method:** Interpolation from map
Location Description: Border Winds Wind Energy Project Site. Near Turbine 32

Submitted By: Shabeeb Abdul Khader **Affiliation:**
Address: 10707 52nd Ave
City: Rolla **State:** ND **Zip:** 58367

Received By:

Contact Person: Shabeeb Abdul Khader
10707 52nd Ave
Rolla , ND 58367

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Anti freeze

Description of Released Contaminant: Anti Freeze

Volume Spilled: 4.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Tear on the thread on radiator cap causing the antifreeze to flow out.

Risk Evaluation:

None

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

The spoil was collected in a loader and taken off to the subcontractors disposal area.

Wastes Disposal Location: Subcontractors spoil bin

Agencies Involved:

Updates

Date: 9/30/2014 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

Small volume spill of antifreeze. However, disposal may need followup.